IIIH PM Op Data Review Fourth Round of IIIH PM Tests



Overview

- The IIIH Task Force has Performed a Preliminary Review of the Following:
 - Controlled Parameters
 - QI's
 - Non-controlled Parameters
- Parameters and QI's Identified as Having Anomalies were Addressed by the Industry Test Labs.



Controlled Parameters

- Controlled Parameters Identified:
 - Fuel Temperature CMIR–106791
 - Fuel Temperature CMIR–106776
 - Left Exhaust Back Pressure CMIR–106781



IIIH QUALITY INDEX OPERATIONAL REVIEW Fuel Inlet Temperature – Degrees C (CONTROL) LAB= D Stand= OB106 CNIR= 106791



http://astmtmc.cmu.edu



- Fuel Temperature QI
 - The control loop is at the limit of control and highly dependent on ambient effects due to the return– less fuel system.



IIIH QUALITY INDEX OPERATIONAL REVIEW Fuel Inlet Temperature - Degrees C (CONTROL) LAB= A Stand= 2 CNIR= 106776



- Fuel Temperature QI
 - Control issues were experienced due to ambient temperature effects.



IIIH QUALITY INDEX OPERATIONAL REVIEW Exhaust Back Pressure Left -- kPa (CONTROL) LAB= E Bland= 3 CMR= 106761





- Left Exhaust Back Pressure QI
 - Exhaust back-pressure valve actuator lower limit was spanned Incorrectly which prevented it from opening fully to lower the exhaust back pressure. It was corrected at test hour 5 by test Engineer. This test did end with a positive QI (0.429).



Non-controlled Parameters

Non-Controlled Parameters Identified:

- Oil Pump Temperature CMIR 106781
- Oil Sump Temperature CMIR 106781
- Left and Right Exhaust Temperature CMIR 106791
- Left and Right NOx CMIR 106777
- Left and Right NOx CMIR 106779















Oil Pump Temperature

- Found -1.3°C offset relative to T-block control temp. Large ambient temp. swings were also observed (75F to 57F for 1st 2 days and 80 F to 47 F for last 2 days) believed to be cause of undulations observed.
- Oil Sump Temperature
 - Found -1.3°C offset relative to T-block control temp. This thermocouple might have been in the wrong drain plug hole (on the side of pan instead of under-bottom of the pan). These exceptions believed to have been the cause of Oil Sump Temp. showing lower than others.
- NOx Left and Right

 NOx gas analysis was performed manually and not with a real time NOx sensor.

- Right and Left Exhaust Temperature
 - Fans are utilized per procedure to cool the exhaust turndown pipes. This parameter is also highly dependent on thermocouple insertion depth.
- NOx Left and Right
 - NOx gas analysis was performed manually and not with a real time NOx sensor.



Questions?

