Date: November 25, 2025

To: ASTM Testing Laboratories

From: Jason Bowden / OH Technologies,

Inc.

Re: OHT Technical Memo 06

OHT3H-001-1 PHASER, INTAKE (BC 6)

Cc: Mr. Dylan Beck / Test Monitoring Center

Mr. Robert Stockwell / Seq. III Surveillance Panel Chair

This Technical Memo is intended to notify users of the ASTM Seq. IIIH Test Method that OHT was notified by a laboratory that they located a few, BC6, OHT3H-001-1 Intake Fixed Phasers that appear to have minimal engagement with the casing and a smaller diameter pin. Please find below a photo sample:

Larger diameter pin & increased engagement of casing.



Smaller diameter pin & minimal engagement with casing.

In order to inspect for this issue, the cover on the phaser must be removed. OHT is requesting that laboratories either return to OHT or inspect the BC 6 Intake Phasers. Please return any questionable material to OHT.

OHT has suspended shipment of BC 6 intake and exhaust phasers until this issue has been resolved with the manufacturer.

If there are any questions or comments regarding the aforementioned item, please do not hesitate to contact me.

Best regards,

Jason H. Bowden OH Technologies, Inc.