

- Meeting was called to discuss the rating process for the new 31XX AAM hardware
- Are raters using the previous rating templates on the new 31XX hardware parts even though they are dimensionally different?
 - Raters have not had a situation yet where the transparent rating template were need to rate 31XX hardware
 - Agreement that a new set of L-33-1 rating templates are needed for the 31XX hardware
 - Not only for the side gear, but also for the contact areas on the differential case.
- Action items:
 - Raters will not use the old rating templates for the 31XX hardware
 - New rating templates will be developed for the new 31XX hardware

If a cover plate rating template is still needed it is available for purchase from AP services (Part #1000214946).

AP Services 18001 Sheldon Road Middleburg Heights, OH 44130 T: 724.295.6200 I F: 724.295.6201 www.cwnuclear.com/brands/ap-services