

Date: 25 OCT 2004

To: ASTM Sequence III Testing Laboratories

From: Jason H. Bowden / OH Technologies, Inc.

Re: Seq. III CPD Technical Memo 10
BC 4, OHT3G-059-1, IIIG VALVE SPRING NOT PAINTED

Cc: Mr. Sid Clark / General Motors Powertrain
Mr. Michael Kasimirsky / Test Monitoring Center

BC 4, OHT3G-059-1 IIIG, SPRING, VALVE (COLOR CODE PINK) NOT PAINTED

Please be advised that the BC 4, IIIG valve spring has not been color coded pink. The spring is laser etched on the bottom with the following, "IIIG BC4 P2=210." Future batches will once again be color coded pink.

If there are any questions or comments regarding the aforementioned item, please do not hesitate to call.