



#### **Cummins M11 Filter Plugging**


- Oronite has observed variable filter performance in recent testing
- Filters have been examined to determine cause
- We observe that filters with high pressure have had the pleats glued together



# ATTACHMENT 9, 2 OF3

### **ORONITE**

#### **M11EGR Filters**





## ATTACHMENT 9, 3 OF3

### **ORONITE**

#### Recommendations

Improve filter pleat spacing consistency

